


Suzuki M800 2010-UP Art. no. 493-607/807 Forward control



Turn



This accessory should be mounted by a professional mechanic only, Motolux International B.V. / Highway Hawk can not be held responsible for improper installation

Revised # 2

Please check all fixings and mounting points before assembly as listed on the mounting instruction sheet.

Barneveld - The Netherlands

23

© MotoLux Specialties B.V.