
## HIGHY/AY HAVYK

## Taillight with integrated turnsignals

## Yamaha XVS 950A

<u> Art.no. 682-100</u>

Note: removing OEM (rear) turnsignals or change to LED, requires use of replacement Highway Hawk relay 68-2525



- 1) License plate light (Blue / Black)
- 2) Turnsignal Left (Brown / Black)
- 2) Turnsignal Right (Green / Black)

This accessory should be mounted by a professional mechanic only.

MotoLux International B.V. / Highway Hawk can not be held responsible for improper installation.

© Moto-Lux Specialties B.V. Barneveld - The Netherlands